

US EPA RECORDS CENTER REGION 5



466422

Photographic Log

6/29/89 - ~~8/1/89, 6/15/90~~  
9/7/89


IA - American Chemical Service

AMERICAN CHEMICAL SERVICES

Photographs Roll #1  
29 June to July 7, 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R1-1	06/29/89	Geophysics grid on northern portion of fenced in plant property.
R1-2	06/30/89	Tom Pederson of Warzyn, Inc. taking a reading using EM-31 survey around decon pad.
R1-3	06/30/89	Tom Pederson of Warzyn, Inc. taking a reading using EM-31 survey around decon pad.
R1-4	07/6/89	Decon pad.
R1-5	07/6/89	ETI and drilling rig.
R1-6	07/6/89	ETI setting piezometer.
R1-7	07/6/89	Soil sample - split-spoon setting piezometers.
R1-8	07/7/89	Tim Maley testing soil with HNu while installing piezometers.

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



50th Century Plastics  
1-800-421-4662  
STOCK # APV840-000

R1-1

2 H N H 17 01 SSC

R1-3

2 H N H 17 01 SSC

R1-4

2 H N H 17 01 SSC

2 H N H 17 01 SSC



R1-5

355 PD 17 N N H 1 7

R1-7

355 PD 17 N N H 1 7

R1-8

355 PD 17 N N H 1 7

355 PD 17 N N H 1 7

R1-6

AMERICAN CHEMICAL SERVICES

Photographs Roll #2  
11 July - 18 July 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R2-1	07/11/89	P-15, drilling onto leachate & garbage, view to south.
R2-2	07/11/89	P-15, drilling onto leachate & garbage, view to south.
R2-3	07/18/89	MW-6, drilling initial 5 feet, view to north.
R2-4	07/18/89	MW-6, open split-spoon, 21 to 22.5 feet.
R2-5	07/18/89	MW-6, drilling 20 to 25 ft interval, view to northwest.

AMERICAN CHEMICAL SERVICES

Photographs Roll #3  
26 July to 1 August 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R3-1	07/26/89	AP-6, drilling to 5 feet, view to southwest.
R3-2	07/26/89	AP-8, drilling to 5 feet, view to north.
R3-3	07/27/89	AP-15, 5 to 10 foot auger-solvent coated, view to southwest.
R3-4	07/27/89	AP-15, 5 to 10 foot auger-solvent coated, view to southwest.
R3-5	07/27/89	Drill rig moving into position for AP-24.
R3-6	07/27/89	Drill rig moving into position for AP-24.
R3-7	07/28/89	LW-3, WEI collecting VOA sample.
R3-8	07/28/89	LW-3 WEI collecting BNA sample.
R3-9	07/28/89	LW-3 WEI collecting BNA sample.
R3-10	08/01/89	SB-03 Attempt to drill, view to south.
R3-11	08/01/89	SB-03 Attempt to drill, view to southeast.
R3-12	08/01/89	SB-04 Open split-poon, 2 to 4 ft.
R3-13	08/01/89	SB-04 WEI sampling tarry substance.

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



R2-1

3 1 N N N 2 1 9 6 S S C

R2-3

3 1 N N N 2 1 9 6 S S C

R2-2

3 1 N N N 2 1 9 6 S S C

R2-4

3 1 N N N 2 1 9 6 S S C



R2-5

2 1 N N N 21 58 538

R3-2

2 1 N N N 21 58 538

R3-1

2 1 N N N 21 58 538

R3-3

2 1 N N N 21 58 538

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



R3-4

© 1984 by J. S. S&S

R3-6

© 1984 by J. S. S&S

R3-5

© 1984 by J. S. S&S

R3-7

© 1984 by J. S. S&S



R3-8

2 1-N N N 21 S1 S56

R3-10

2 1-N N N 21 S1 S56

R3-9


2 1-N N N 21 S1 S56

R3-11

2 1-N N N 21 S1 S56







STOCK # 69V84  
1-800-451-4885  
50th CENTURY PLASTICS

#4 R4

3 1-N N N 21 91 556

#2 R4

3 2-N N N 21 91 556

#3 R4

3 2-N N N 21 91 556

#1 R4

3 2-N N N 21 91 556



STOCK # APV840-000  
1-800-431-4665  
50th Century Plastics

#8 R4

0 3 N N N 2 1 9 1 5 5 8

#6 R4

0 3 N N N 2 1 9 1 5 5 8

#7 R4

0 3 N N N 2 1 9 1 5 5 8

#5 R4

0 3 N N N 2 1 9 1 5 5 8



STOCK # APV840-000  
1-800-451-4ees  
50th Century Plastics

#12 R4

3 3-N N 21 91 558

#10 R4

3 3-N N 21 91 558

#11 R4

3 3-N N 21 91 558

#9 R4

3 3-N N 21 91 558



STOCK # APV840-000  
1-800-154-008-1  
50th Century Plastics

#16 R4

355 16 17 NN R-2

#14 R4

355 16 17 NN R-2

#15 R4

355 16 17 NN R-2

#13 R4

355 16 17 NN R-2



STOCK # APV840-000  
1-800-451-0000  
50th Century Plastics

#21 R4

21NNN2191556

#18 R4

21NNN2191556

#19 R4

21NNN2191556

#17 R4

21NNN2191556



50th Century Plastics  
1-800-424-1244  
APV840-000 \*STOCK

#25 RA

2 1 N N N 2 1 9 1 5 5 6

#23 RA

2 1 N N N 2 1 9 1 5 5 6

#24 RA

2 1 N N N 2 1 9 1 5 5 6

#22 RA

2 1 N N N 2 1 9 1 5 5 6



STOCK # ABV840-000  
1-800-451-4885  
50th Century Plastics

#29 R4

2 1 N N N 2 1 9 1 S S E

#27 R4

2 1 N N N 2 1 9 1 S S E

#28 R4

2 1 N N N 2 1 9 1 S S E

#26 R4

2 1 N N N 2 1 9 1 S S E



STOCK # APL840-000  
1-800-451-4665  
50th CENTURY PLASTICS

#33 R4

2 3-N N 21 91 55E

#31 R4

2 3-N N 21 91 55E

#32 R4

2 3-N N 21 91 55E

#30 R4

2 3-N N 21 91 55E



STOCK # ABV840-000  
1-800-451-4005  
50th Century Plastics

#37 R4

2 2-N N N 21 91 558

#35 R4

2 2-N N N 21 91 558

#36 R4

2 2-N N N 21 91 558

#34 R4

2 2-N N N 21 91 558



# 38 R4

0 3 4 4 4 4 1 9 1 5 5 8

AMERICAN CHEMICAL SERVICES

Photographs Roll #5  
7 August - 9 August 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R5-1	08/07/89	Augers on Decon Pad ready to be steam-cleaned.
R5-2	08/07/89	ETI steam-cleaning augers.
R5-3	08/07/89	John Murphy of ACS consulting with WEI and ETI.
R5-4	08/07/89	ETI putting in borehole for P-29. View to east.
R5-5	08/07/89	Contaminated cuttings at location P-29.
R5-6	08/07/89	Piezometer P-29 after completed installation
R5-7	08/07/89	Location for Piezometer P-30. View to south.
R5-8	08/07/89	Piezometer P-30 after completed installation.
R5-9	08/07/89	Location for Piezometer P-31. View to east.
R5-10	08/07/89	Level C operation for P-31. WEI taking vinyl chloride reading.
R5-11	08/07/89	Piezometer P-31 after completed installation.
R5-12	08/07/89	Location for auger probe AP-21.
R5-13	08/07/89	Drilling AP-21.
R5-14	08/07/89	Upper 5 feet of AP-21.
R5-15	08/07/89	Backfill AP-21.
R5-16	08/07/89	Location for Auger Probe AP-22.

AMERICAN CHEMICAL SERVICES

Photographs Roll #5  
7 August - 9 August 1989  
(Continued)

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R5-17	08/07/89	Monitoring with HNu AP-22.
R5-18	08/07/89	Backfill AP-22.
R5-19	08/07/89	Cuttings first 6 feet AP-23.
R5-20	08/07/89	Location for Auger Probe AP-22.
R5-21	08/07/89	Last 5 feet of AP-24.
R5-22	08/08/89	Location of piezometer P-33. View to south.
R5-23	08/08/89	Location of piezometer P-34. View to west.
R5-24	08/08/89	Location of piezometer P-35. View to west.
R5-25	08/08/89	Location for piezometer P-36. View to north.
R5-26	08/08/89	Oily solvent on augers from 10 to 15 ft zone of P-36.
R5-27	08/08/89	Location of P-37. 5 to 10 ft zone cuttings. View to south.
R5-28	08/08/89	Location of P-38. View to east.
R5-29	08/08/89	Tim Maley of WEI inspecting decontamination of rig.
R5-30	08/08/89	Boring SB-08, open sample spoon, 4 to 6 foot zone.
R5-31	08/08/89	Boring SB-08, open spoon sample, 8 to 10 foot zone.
R5-32	08/08/89	Boring SB-09a, open spoon sample, 4 to 6 foot zone.

AMERICAN CHEMICAL SERVICES

Photographs Roll #5  
7 August - 9 August 1989  
(Continued)

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R5-33	08/08/89	Boring SB-09, open spoon sample, 2 to 4 foot zone.
R5-34	08/08/89	Boring SB-09, open spoon sample, 4 to 6 foot zone.
R5-35	08/08/89	Location of SB-09a and SB-09. View to east (SB-09a in foreground)
R5-36	08/08/89	Boring SB-09, open spoon sample, 8 to 10 ft. zone.
R5-37	08/09/89	Boring SB-10, open spoon sample, 1 to 3 foot zone.

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



#1 R5

11 99 55C

#3 R5

11 99 55C

#2 R5

11 99 55C

#4 R5

11 99 55C



#5 R5

2 N N N N 11 99 550

#7 R5

2 N N N N 11 99 550

#6 R5

2 N N N N 11 99 550

#8 R5

2 N N N N 11 99 550



#9 R5

2 NNNN 11 99 358

#11 R5

2 NNNN 11 99 358

#10 R5

2 NNNN 11 99 358

#12 R5

2 NNNN 11 99 358



#13 R5

2025 09 11 11:44 AM

#15 R5



2025 09 11 11:44 AM

#14 R5

2025 09 11 11:44 AM

#16 R5

2025 09 11 11:44 AM



#17 RS

253 66 11 99 358

#19 RS

253 66 11 99 358

#18 RS

253 66 11 99 358

#20 RS

253 66 11 99 358

20th Century Plastics  
1-800-421-4662  
STOCK # PPV34



#21 R5

255 66 11 11 11 11

#23 R5

255 66 11 11 11 11

#22 R5

255 66 11 11 11 11

#24 R5

255 66 11 11 11 11

20th Century Plastics  
1-800-421-4662  
STOCK # FPV64



#25 R5

2 N N N N 11 99 558

#27 R5

2 N N N N 11 99 558

#26 R5

2 N N N N 11 99 558

#28 R5

2 N N N N 11 99 558

Century Plastics  
1-800-421-4662  
STOCK # FPV64



#29 R5

2000-01-01 99 550

#31-R5

2000-01-01 99 550

#30 R5

2000-01-01 99 550

#32 R5

2000-01-01 99 550

21st Century Plastics  
1-800-421-4662  
STOCK # PPV34



#33 R5

2011 11 99 550

#35 R5

2011 11 99 550

#34 R5

2011 11 99 550

#36 R5

2011 11 99 550



#37 R5

1950-1951

AMERICAN CHEMICAL SERVICES


Photo Roll #6  
 9 August - 10 August 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R6-1	08/09/89	SB-10, open split-spoon 3 to 5 ft depth.
R6-2	08/09/89	SB-10, open split-spoon 6 to 8 ft depth.
R6-3	08/09/89	SB-10, open split-spoon 8 to 10 ft depth.
R6-4	08/09/89	SB-10, location, view to south.
R6-5	08/09/89	SB-11, open split-spoon 1 to 3 ft depth.
R6-6	08/09/89	SB-11, open split-spoon 3 to 5 ft depth.
R6-7	08/09/89	SB-11, open split-spoon 6 to 8 ft depth.
R6-8	08/09/89	SB-11, open split-spoon 8 to 10 ft depth.
R6-9	08/09/89	SB-11, location, view to east south east.
R6-10	08/09/89	SB-12, open split-spoon 1 to 3 ft depth.
R6-11	08/09/89	SB-12, open split-spoon 3 to 5 ft depth.
R6-12	08/09/89	SB-12, open split-spoon 5 to 7 ft depth.
R6-13	08/09/89	SB-12, open split-spoon 8 to 10 ft depth.
R6-14	08/09/89	SB-12, location, view to west.
R6-15	08/09/89	SB-13, open split-spoon 1 to 3 ft depth.
R6-16	08/09/89	SB-13, open split-spoon 3 to 5 ft depth.
R6-17	08/09/89	SB-13, open split-spoon 6 to 8 ft depth.
R6-18	08/09/89	SB-13, open split-spoon 6 to 8 ft depth.
R6-19	08/09/89	SB-13, open split-spoon 8 to 10 ft depth.
R6-20	08/09/89	SB-13, location, view to south.
R6-21	08/09/89	SA-3-B11a, location, view to northeast.

AMERICAN CHEMICAL SERVICES

Photo Roll #6  
9 August - 10 August 1989  
(Continued)

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R6-22	08/09/89	SA-3-B11a, open split-spoon, 1 to 3 ft depth.
R6-23	08/09/89	SA-3-B12a, location, view to southwest.
R6-24	08/10/89	P-39, location view to south southwest.
R6-25	08/10/89	P-39, view of stained cuttings.
R6-26	08/10/89	P-40, location, view to northeast.
R6-27	08/10/89	P-41, location, view to northwest.
R6-28	08/10/89	P-41, cuttings view to west.
R6-29	08/10/89	Sa-3-B11, location, view to northeast.
R6-30	08/10/89	SA-3-B11, open split-spoon 1 to 3 ft depth.
R6-31	08/10/89	SA-3-B12, location view to northwest.
R6-32	08/10/89	SA-3-B12, open split-spoon 1 to 3 ft depth.
R6-33	08/10/89	SA-3-B13, location, view to southeast.
R6-34	08/10/89	SA-3-B13, open split-spoon, 1 to 3 ft depth.
R6-35	08/10/89	SA-3-B13, open split-spoon, 3 to 5 ft depth.
R6-36	08/10/89	SA-3-B14, location, view to southeast.



#1 R6

2 14144 N 00 29 55C

#3 R6

#2 R6

2 14144 N 00 29 55C

#4 R6

2 14144 N 00 29 55C

STOCK # PBV84  
1-800-451-4885  
1-800-451-4885

20th Century Plastics  
1-800-421-4662  
STOCK # PPV84



#5 R6

0 14 11 11 20 29 55E

#7 R6

0 14 11 11 20 29 55E

#6 R6

0 14 11 11 20 29 55E

#8 R6

0 14 11 11 20 29 55E

20th Century Plastics  
1-800-421-4662  
STOCK # PPV84



#9 R6

255 62 00 29 556

#11 R6

255 62 00 29 556

#10 R6

255 62 00 29 556

#12 R6

255 62 00 29 556



#13 R6

#15 R6

#14 R6

#16 R6

20th Century Plastics  
1-800-421-4662  
STOCK # PPV84



#17 RG

© 1999 N N 20 29 SSC

#19 RG

© 1999 N N 20 29 SSC

#18 RG

© 1999 N N 20 29 SSC

#20 RG

© 1999 N N 20 29 SSC

20th Century Plastics  
1-800-421-4662  
STOCK # PPV84



50th Century Plastics  
1-800-421-4682  
STOCK # PPV84

#21 R6

© 1984 H. W. Wilson & Co.

#23 R6

© 1984 H. W. Wilson & Co.

#22 R6

© 1984 H. W. Wilson & Co.

#24 R6

© 1984 H. W. Wilson & Co.

20th Century Plastics  
1-800-421-4662  
STOCK # PPV84



#25 R6

255 67 02 HHH 29 550

#27 R6

255 67 02 HHH 29 550

#26 R6

255 67 02 HHH 29 550

#28 R6

255 67 02 HHH 29 550



#29 RG

255 67 02 H N N 2

#31 RG


255 67 02 H N N 2

#30 RG

255 67 02 H N N 2

#32 RG

255 67 02 H N N 2



#33 R6

2 N N N N 20 29 55E

#35 R6

2 N N N N 20 29 55E

#34 R6

2 N N N N 20 29 55E

#36 R6

2 N N N N 20 29 55E

AMERICAN CHEMICAL SERVICES

Photographs Roll #7  
8 August to 16 August 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R7-1	08/10/89	SA-3-B14, open split-spoon 1 to 3 feet.
R7-2	08/10/89	SA-3-B15, location, view to southeast.
R7-3	08/10/89	SA-3-B15, open split-spoon 1 to 3 feet.
R7-4	08/10/89	SB-4a, location view to northwest.
R7-5	08/10/89	SB-4a, open split-spoon 13 to 15 feet.
R7-6	08/10/89	SB-4a, open split-spoon 17 to 19 feet.
R7-7	08/15/89	TP-1, beginning excavation view to northeast.
R7-8	08/15/89	TP-1, beginning excavation view to southeast.
R7-9	08/15/89	TP-1, excavation 1 to 3 ft, view to northeast.
R7-10	08/15/89	TP-1, excavation acetylene tank & drum debris, view to northeast.
R7-11	08/15/89	TP-1, WEI sampling waste (ACS-TP-1-3.5) view to northeast.
R7-12	08/15/89	TP-1, excavation to 5 feet, view to northwest.
R7-13	08/15/89	TP-1, excavation to 5 feet, view to north.
R7-14	08/15/89	TP-1, WEI sampling natural soils (ACS-TP-1-6.5), view to northwest.
R7-15	08/15/89	TP-1, backfilling waste, view to northwest.
R7-16	08/15/89	TP-1, backfilled pit, view to northwest.
R7-17	08/15/89	TP-2, beginning excavation, view to south.

AMERICAN CHEMICAL SERVICES

Photographs Roll #7  
8 August to 16 August 1989  
(Continued)

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R7-18	08/15/89	TP-2, drums excavated 2 to 4 ft, view to south.
R7-19	08/15/89	TP-2, drums excavated 2 to 4 ft, view to south.
R7-20	08/15/89	TP-2, WEI sampling waste, view to south.
R7-21	08/15/89	TP-2, drum with waste pouring out, view to southwest.
R7-22	08/15/89	TP-2, close up pit 4 to 5 ft, view to southeast.
R7-23	08/10/89	TP-2, close up pit 4 to 5 ft, view to west.
R7-24	08/10/89	TP-2, close up pit 6 to 7 ft. view to west.
R7-25	08/10/89	TP-2, WEI sampling natural soils, view to south.
R7-26	08/10/89	TP-2, stacked excavated drums, view to east.
R7-27	08/10/89	TP-2, solvent waste from drums, view to northeast.
R7-28	08/10/89	TP-2, solvent waste floating on standing water.
R7-29	08/10/89	TP-2, backfilling and scraping TP-2.
R7-30	08/16/89	TP-3, beginning excavation, view to south.
R7-31	08/16/89	TP-3, 2 to 3 feet, view to northwest.
R7-32	08/16/89	TP-3, open pit, view to southwest.
R7-33	08/16/89	TP-3, open pit 6 to 7 feet, view to south.

AMERICAN CHEMICAL SERVICES

Photographs Roll #7  
8 August to 16 August 1989  
(Continued)

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R7-34	08/16/89	TP-3, open pit 6 to 7 feet, note beginning of cave, view to southwest.
R7-35	08/16/89	TP-3, open pit 8 to 9 feet solvent waste seeping in, view to southwest.
R7-36	08/16/89	TP-3, open pit 8 to 9 feet solvent waste seeping in, view to southwest.

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-1

R7-3

R7-2

R7-4

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-5

2 1-N N N 30 22 55K

R7-7

2 1-N N N 30 22 55K

R7-6

2 1-N N N 30 22 55K

R7-8

2 1-N N N 30 22 55K

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-9

358 11 11 11 11 11

R7-11

358 11 11 11 11 11

R7-10

358 11 11 11 11 11

R7-12

358 11 11 11 11 11

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-13

1-800-421-4662

R7-15

1-800-421-4662

R7-14

1-800-421-4662

R7-16

1-800-421-4662

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



R7-17

2 14444 20 22 55X

R7-19

2 14444 20 22 55X

R7-18

2 14444 20 22 55X

R7-20

2 14444 20 22 55X

20th Century Plastics  
1-800-421-4662  
STOCK# APV840-000



R7-21

2 14 N N 30 22 55X

R7-23

2 14 N N 30 22 55X

R7-22

2 14 N N 30 22 55X

R7-24

2 14 N N 30 22 55X

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-25

355 77 02 N N-1 2

R7-27

355 77 02 N N-1 2

R7-26

355 77 02 N N-1 2

R7-28

355 77 02 N N-1 2

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R7-29

2 2-N N 2 2 22 536

R7-31

2 2-N N 2 2 22 536


R 7-30

2 2-N N 2 2 22 536

R7-32

2 2-N N 2 2 22 536

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000





AMERICAN CHEMICAL SERVICES

Photographs, Roll #8  
16 August - 17 August, 1989

<u>Page No.</u>	<u>Date</u>	<u>Description</u>
R8-1	08/16/89	TP-3, WEI sampling waste (ACS-TP-3-9) view to southwest.
R8-2	08/16/89	TP-3, WEI sampling waste (ACS-TP-3-9). View to northwest.
R8-3	08/16/89	TP-3, WEI sampling waste (ACS-TP-3-9) View to west.
R8-4	08/16/89	TP-3, pit at 10-11 feet, view to southwest.
R8-5	08/16/89	TP-3, WEI measuring pit, view to southeast.
R8-6	08/16/89	TP-3, waste saturated soil.
R8-7	08/16/89	TP-3, backfilled pit. TP4 location in background.
R8-8	08/16/89	Staff gage in fire pond, view to southwest.
R8-9	08/16/89	TP-4, beginning of excavation, view to southeast.
R8-10	08/16/89	TP-4, excavation at 5 feet, view to southeast.
R8-11	08/16/89	TP-4, Pit at 5 feet, view to east.
R8-12	08/16/89	TP-4, WEI sampling waste (ACS-TP-4-8) view to north.
R8-13	08/16/89	TP-4, WEI sampling waste, view to northwest.
R8-14	08/16/89	TP-4, pit at 8 feet (caved), view to northwest.
R8-15	08/16/89	TP-4, backfilling TP-4, view to north.

AMERICAN CHEMICAL SERVICES

Photographs, Roll #8  
16 August - 17 August, 1989  
(Continued)

<u>Page No.</u>	<u>Date</u>	<u>Description</u>
R8-16	08/17/89	TP-4, backfilled pit. TP-5 location in background, view to north.
R8-17	08/17/89	TP-5, drums and waste excavated 2-3 feet, view to east.
R8-18	08/17/89	TP-5, excavation to 4 feet, view to northwest.
R8-19	08/17/89	TP-5, pit at 4 feet, view to northeast.
R8-20	08/17/89	TP-5, WEI sampling waste, view to northwest.
R8-21	08/17/89	TP-5, WEI sampling waste, view to northeast.
R8-22	08/17/89	TP-5, view of pit, view to northeast.
R8-23	08/17/89	TP-5, WEI sampling waste, view to southeast.
R8-24	08/17/89	TP-5, view of pit, view to northeast.
R8-25	08/17/89	TP-5, backfilled TP-3, TP-4, TP-5, view to south.
R8-26	08/17/89	TP-6, location for Tp-6 3 ft excavation, view to north.
R8-27	08/17/89	TP-6, blue sludge out of punctured drum, view to southwest.
R8-28	08/17/89	TP-6, blue sludge out of punctured drum, view to southwest.
R8-29	08/17/89	TP-6, WEI sampling waste, view to west.
R8-30	08/17/89	TP-6, blue sludge in pit, view to north.

AMERICAN CHEMICAL SERVICES

Photographs, Roll #8  
16 August - 17 August, 1989  
(Continued)

<u>Page No.</u>	<u>Date</u>	<u>Description</u>
R8-31	08/17/89	TP-6, WEI sampling waste, view to southeast.
R8-32	08/17/89	TP-6, backfilled pit, view to north.
R8-33	08/17/89	TP-7, initial excavation, view to southwest.
R8-34	08/17/89	TP-7, drum excavated, view to south.
R8-35	08/17/89	TP-7, pit at 3 feet, view to north.
R8-36	08/17/89	TP-7, WEI sampling drum, view to southwest.
R8-37	08/17/89	TP-7, WEI sampling waste, view to southwest.

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-1

25E 15 00 51 55X

R8-3

25E 15 00 51 55X

R8-2


25E 15 00 51 55X

R8-4

25E 15 00 51 55X

~~R8-4~~

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-5

R8-7

2000-00-00 00:00:00

~~88~~

R8-6

2000-00-00 00:00:00

R8-8

2000-00-00 00:00:00

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-9

R8-11

R8-10

R8-12

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-13

2 1-N N 30 92 550

R8-15

2 1-N N 30 92 550

R8-14

2 1-N N 30 92 550

R8-16

2 1-N N 30 92 550

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-17

South Century Plastics  
1-800-451-4665  
STOCK # APV840-000

R8-19

R8-18

R8-20

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000





20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R8-25

2 14 11 11 00 52 558

R9-27

2 14 11 11 00 52 558

R9-26

2 14 11 11 00 52 558

R9-28

2 14 11 11 00 52 558

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R9-29

255 25 02 11 41 2

R9-31

255 25 02 11 41 2

R9-30

255 25 02 11 41 2

R9-32

255 25 02 11 41 2

20th Century Plastics  
1-800-421-4662  
STOCK # APV840-000



R9-33

2 1-N N 20 52 556

R9-35


2 1-N N 20 52 556

R9-34

2 1-N N 20 52 556

R9-36

2 1-N N 20 52 556



R9-37

1941 11 13

AMERICAN CHEMICAL SERVICES


Photo Roll #9  
7 September 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R9-1	09/07/89	AP-36, site location view to south.
R9-2	09/07/89	AP-36, auger probe to 5 ft depth.
R9-3	09/07/89	AP-36, sediment on auger flights from 0 to 10 ft depth.
R9-4	09/07/89	AP-37, site location view to southeast.
R9-5	09/07/89	AP-37, sediment on auger flights from 0 to 5 ft depth.
R9-6	09/07/89	AP-37, sediment on auger flights from 5 to 10 ft depth.
R9-6A	09/07/89	Not applicable.
R9-7	09/07/89	AP-38, site location view to south.
R9-8	09/07/89	AP-38, cuttings from augering 0 to 10 ft depth.
R9-9	09/07/89	AP-38, sediment on auger flights 0 to 10 ft depth.
R9-A	09/07/89	Not applicable.
R9-10	09/07/89	AP-39, cuttings from augering 0 to 5 ft depth.
R9-11	09/07/89	AP-39, new site location view to northeast.
R9-12	09/07/89	AP-39, sediment on auger flights from 0 to 10 ft depth.
R9-13	09/07/89	SB-14, site location view to northeast.
R9-14	09/07/89	SB-14, open split-spoon 10 to 11.5 ft depth.
R9-15	09/07/89	SB-15, open split-spoon 12 to 14 ft depth.

AMERICAN CHEMICAL SERVICES

Photo Roll #9 (Cont.)  
7 September 1989

<u>Photo No.</u>	<u>Date</u>	<u>Description</u>
R9-16	09/07/89	SB-16, site location view to east.
R9-17	09/07/89	SB-16, open split-spoon 5 to 7 ft depth.



R9-3

Z N N N N 2 1 9 2 5 5 0

R9-1

Z N N N N 2 1 9 2 5 5 0


R9-4

Z N N N N 2 1 9 2 5 5 0

R9-2

Z N N N N 2 1 9 2 5 5 0

50th Century Plastics  
1-800-451-4883  
STOCK # APV840-000



R9-6

ZNNNN 21 92 558

R9-5

ZNNNN 21 92 558


R9-7

ZNNNN 21 92 558

R9-6A

ZNNNN 21 92 558

50th Century Plastics  
1-800-421-4882  
STOCK # APV840-000



R9-9A

2 26 17 N N N 1 2

R9-8

2 26 17 N N N 1 2

~~R9-9~~ R9-10

2 26 17 N N N 1 2

R9-9

2 26 17 N N N 1 2

STOCK # APV840-000  
1-800-421-4882  
50th Century Plastics



R9-13

2 1 N N N 21 92 558

R9-11

2 1 N N N 21 92 558

R9-14

2 1 N N N 21 92 558

R9-12

2 1 N N N 21 92 558

50th Century Plastics  
1-800-421-4882  
STOCK # APV840-000



R9-17

2 1-N N N 21 92 558


R9-15

2 N N N N 21 92 558

R9-16

2 N N N N 21 92 558

VI




CRUDE & FINISHED  
SOLVENT STORAGE  
11-13-80



SOLVENT RECYCLING PLANT  
11-13-80



CRUDE & FINISHED FUEL  
STORAGE AREA  
11-13-80



CRUDE & FINISHED FUEL  
STORAGE AREA  
11-13-80